DCSI – NISC MultiSpeak Integration at Pioneer Electric Cooperative

MultiSpeak User's Conference 2007


Presented by: John Hickman







About Pioneer



2,580 miles of line
 16,200 meters
 107 MW Demand



Pioneer as a Beta Site

- Started testing the MultiSpeak integration efforts between DCSI and NISC in July 2006
- Work was done on both the CIS and the OMS interfaces
- Served the role of working between the two venders
 - Troubleshooting
 - Educating the programmers on the other system



AMR at Pioneer


- Started installing a DCSI's TWACS system August 2005
- New AMR system is an extension of Pioneer's Distribution Automation out to the meter
- Used NISC's Mobile Data Solution for paperless meter exchange

Integration of AMR into Pioneer's Business Systems

- Single entry of data
- Paperless system
- NISC's Mobile Data solution
- AMR meter exchange process has been a non-event for office staff
- Estimated 2 man-years of labor savings (\$84,000)









CIS Integration

- On demand meter reading
- Meter add in AMR system real time from iVUE (Work in progress)
- Updating of Substation, Feeder and Phase information from AMR system to CIS

💡 37001dbs 37001 - Pio	oneer Electric Coopera	tive NISC CIS Cus	tomer Care									
<u>File View Application My</u> Fa	vorites Tools <u>H</u> elp											
K Back > Forward Jump Job		utage E-Bill Create C	ontact Auto Create	Contact Zoom Ma	oView							R: 🧐
F <u>i</u> nd:	Search Type: Name	🗾 Last: JOHNS(DN Fin	st: JAMES								Sear <u>c</u> h
Customer Management	Readings : JOHNSON	JAMES, Cust#:	43575							Custome	r Level Set Aside Re	trieve (0) 🔻
🗉 🛅 Billing/Accounts Receiva	Account Service Provide	er Serv Loc #	Primary Desc 🔺	Mtr Pos	Meter# S	ec Meter#	Stat Meter Type Config	Conn Mtr Pos	De	escription	Emer Addr	
🗄 💼 Capital Credits	271202 ELEC COOP	2712 089-08			39650492		1 0 - KWH - Nor			PL - NO ELEC HE		6133 E
	1509300 ELEC COOP	15093 090-00	-004	1	39650364		1 0 - KWH - Nor	0 N	O LARGE AP	PL - NO ELEC HE	AT	6895 F
Payments/Readings												
E-Bill Payments/Readinc												
EFT - (0) Payments/Readings	<											>
Readings	Readings Meter Service Po	sted History AMR/Inte	erval History									
-Transaction History	AMR Type: DCSI						Read Now					
Equipment Management	Meter ID: 9164175	Port Number:					Reau Now					
📄 Location Management	Interval Reading Date/Time		Reg Set Reading	Demand Rdg	KVAR Reading AMR F	Rda Blink Co	ount Post Process Date/Ti	ve@jeneelL_em	Billable Rdo	Meter#	Rdg # Rdg Activity	
Administration	11/02/2006 15:27:21		1 437:	_	0.00/WS		11/02/2006 15:2			39650492	0 R - Regular	~
🚞 Reports	11/02/2006 14:47:16		1 437:		0.00WS		11/02/2006 14:4			39650492	0 R - Regular	
🚞 Processes	11/02/2006 14:25:00		1 4373		0.00WS		11/02/2006 14:2			39650492	0 R - Regular	
	11/02/2006 14:24:20 11/02/2006 00:14:19		1 437:		0.00WS 0.00WS		11/02/2006 14:2 11/02/2006 00:1		>	39650492 39650492	0 R - Regular 0 R - Regular	=
	11/02/2006 00:14:00	11/02/2000 00:14:13	1 4370		0.00 OK		11/02/2000 00.1	61	~	39650492	0 R - Regular	
	11/01/2006 00:14:00		1 4363		0.00 OK			68		39650492	0 R - Regular	
	10/31/2006 00:14:00		1 435		0.00 OK			47	>	39650492	0 R - Regular 0 R - Regular	
	10/30/2006 00:29:00 10/29/2006 00:15:00		1 4353 1 4343		0.00 OK 0.00 OK			<u>65</u>	~	39650492 39650492	0 R - Regular	
	10/28/2006 00:14:00		1 433		0.00 OK			62		39650492	0 R - Regular	
	10/27/2006 00:14:00		1 4333		0.00 OK			63		39650492	0 R - Regular	
	10/26/2006 00:14:00 10/25/2006 00:15:00		1 4326		0.00 OK 0.00 OK			73	>	39650492 39650492	0 <mark>R - Regular</mark> 0 R - Regular	
	10/24/2006 00:14:00		1 431		0.00 OK			52	- V	39650492	0 R - Regular	
	10/23/2006 00:14:00		1 4306	33 0.000	0.00 OK			82	\checkmark	39650492	0 R - Regular	
	10/22/2006 00:14:00		1 4290		0.00 OK			55		39650492	0 R - Regular	
	10/21/2006 00:19:00 10/20/2006 00:14:00		1 4293		0.00 OK 0.00 OK			79	>	39650492 39650492	0 R - Regular 0 R - Regular	
	10/19/2006 00:14:00	10/19/2006 00:14:00	1 427		0.00 OK		10/19/2006 15:2		\checkmark	39650492	0 R - Regular	
	10/18/2006 00:15:00		1 4273		0.00 OK		10/19/2006 15:2		\checkmark	39650492	0 R - Regular	
	10/17/2006 00:17:00 10/16/2006 00:20:00		1 4264		0.00 OK 0.00 OK		10/19/2006 15:2			39650492 39650492	0 R - Regular 0 R - Regular	
	10/15/2006 00:18:00		1 424		0.00 OK		10/19/2006 15:2		V	39650492	0 R - Regular	
	10/14/2006 00:15:00		1 423	39 0.000	0.00 OK		10/19/2006 15:2		\checkmark	39650492	0 R - Regular	
< · · · >	10/13/2006 11:25:22		1 4236		0.00WS		10/13/2006 11:2			39650492	0 R - Regular	
Navigation My Favorites	10/13/2006 11:24:42 10/13/2006 00:15:00	10/13/2006 11:24:42	1 4236 1 4234		0.00WS 0.00OK		10/13/2006 11:2 10/19/2006 15:2		V	39650492 39650492	0 <mark>R - Regular</mark> 0 R - Regular	
Alerts	10/12/2006 00:14:00		1 423		0.00 OK		10/19/2006 15:2		~	39650492	0 R - Regular	
	10/11/2006 00:14:00		1 4223		0.00 OK		10/19/2006 15:2		\checkmark	39650492	0 R - Regular	
	10/10/2006 00:14:00		1 421		0.00 OK		10/19/2006 15:2			39650492	0 R - Regular 0 R - Regular	
	10/09/2006 00:14:00 10/08/2006 00:14:00		1 4211		0.00 OK 0.00 OK		10/19/2006 15:2			39650492 39650492	0 R - Regular	
	10/07/2006 00:15:00		1 419		0.00 OK		10/19/2006 15:2		\checkmark	39650492	0 R - Regular	
	10/06/2006 00:14:00		1 419	0.000 8	0.00 OK		10/19/2006 15:2			39650492	0 R - Regular	
	10/05/2006 00:14:00 10/04/2006 00:13:00		1 418:		0.00 OK 0.00 OK		10/19/2006 15:2			39650492 39650492	0 R - Regular 0 R - Regular	
	10/03/2006 00:13:00		1 4176		0.00 OK		10/19/2006 15:2		- V	39650492	0 R - Regular	
	10/02/2006 00:14:00		1 416		0.00 OK		10/19/2006 15:2			39650492	0 R - Regular	~
	Related -											




Data Mapping

- About 20 data fields are shared between the CIS and the AMR system
- Each utility maps their data differently in TWACS AMR database
- About half of the data fields are coming across with the 3.0 integration
- Rest of the fields are being updated with a custom batch process



OMS Integration

- Verify meter outage once call has been received
- Check other meters upstream to determine the extent of the outage
- Check all meters that has been a part of an outage once this outage has been restored
 Uses DCSI's Oasys software for fast pings





Partial Power Outage

W NISC Outage Client - Server srvoms

<u>File A</u>dmin <u>T</u>ools <u>L</u>ook and Feel <u>H</u>elp

C. D' 1 🛛 🖉 🕲 🕹 🕹 🧇

🏙 Outage Entry 🔇 Outage Manager 🛛 🦛 Outage Phone Calls 🖙 Crew Manager

Filter by Substation:	▼ Feed	er:	▼ District	Code:		▼ Custo
Category:	#Outages:	#Calls:	# Out:	Filter Outag	Filter Calls:	Filter Out:
Restored	4	3	469	4	3	469
Crew Not Assigned	2	1	468	2	1	468
Open	0	0	0	0	0	0
All	4	3	469	4	3	469
Crew Assigned	2	2	1	2	2	1

	•															*********			
*	Outage:	Status:	Type:	Time Off:	Line Sect.:	Location:	Phs:	Sub:	Fdr:	# Out:	#Calls:	Comments	Crew:	Medical Alert:	Priority:	Gener	Disp Not	Dist	Pro Dvc:
	43182	Restored	Meter	4:59:09 AM 11/2/2006	2049	092-75-011	В	20	3	1	1	Ø							VSA-5203
	43 81	Restored	Meter	1:26:00 PM 11/1/2006	2448	067-96-003	С	24	3	1	1	P	(23)						RECLOSER-2448
	4,180	Restored	Linesection	10:50:40 AM 11/1/2006	5122		ABC	12	2	467	0			(Ť)			9		5120
	.3179	Restored	No Outage	10:18:00 AM 11/1/2006	2245	2245	А	32	2	0	1		(23)				9		SECTZR-2245

V	Include Blir	nks													
	🕻 <u>N</u> ew	🕅 <u>E</u> dit	🗊 <u>D</u> elete	🖪 <u>S</u> ave	🔲 <u>C</u> ancel						٩	Weather	📒 <u>R</u> eport	å <u>M</u> erge	金 Split
₿.															
1															
Î															
())															
	4 80000000								000000						
	Se Cus	stom 🔐	File Watcher	Prediction				 		 					


📉 🖉 🚊										
Outage#: 43182		Date/Time Off:	11/02/2006	•	🤌 04:59 AM		Connectivity Type:	он		
Number Out: 1		Date/Time On:	11/02/2006		🤌 06:29 AM		Account #:	920703		
Status: Restored	•	Cause:	ACCIDENTS, OTHER			•	Meter#:	46208990		
Type: Meter	•	-	ANCHOR OR GUY					811053621		
Phase: B	•	=	2049				Trf Bank Id:	0		
Location: 092-75-011		Тар:	0				District Cd:			
Connectivity		Actual Nbr Out:					Weather:			•
	Fdr Cd: Pro Dvc:		L				Temperature:			•
B 20 3	VSA-5203	Set Device								
							Windy:			
							Major Storm:			
Dispatch Comments				Crew Info-						
Time:	Comments:		User:	Crew:	Outage:	Time Assigned:	Time On-Sit	te: Time Off-Site:	User:	
		1								
_										
				J I						
	🛱 Add 📋 Delete						🛱 Ado	d <u> î</u> Delete		
🖪 <u>S</u> ave <u>C</u> lose									<u>R</u> eport	<u>O</u> utage Ticket
	* * First Name: Last Name:	Tin	ne Called: User:	Line Sect.: F	Phs: Trf:	Meter:	Service Map Lo		Commonte:	
	* * First Name: Last Name:	4:59:09 AM	111/2/2006 CRC	2049 B	81105362		092-75-011	SAME ACCT HAS NO POWE	Comments: R TO LIGHT IN GARAGE, HE	AT OTHER AREA
									· · · · ·	
🊛 1 🖲 Phone Calls										
🔁 0 🔿 Medical Alert										
9 0 🔿 Priority										
🖀 1 🔾 All Consumers										
🕎 🛛 🔿 Call Back										

Select Outage Event




, r						
	User	▼ Started	Completed	Outage Event Name	Status	Detection 🔼
	NISC	2-Nov-2006 6:29:48 AM	2-Nov-2006 6:30:06 AM	OD_OA-ping	Complete	Ping 🦳
→	NISC	2-Nov-2006 5:02:36 AM	2-Nov-2006 5:02:51 AM	OD_OA-ping	Complete	Ping
≁	NISC	2-Nov-2006 5:02:36 AM	2-Nov-2006 5:06:12 AM	OD_OA-ping	Complete	Ping
	Pioneer	2-Nov-2006 3:30:04 AM	2-Nov-2006 3:36:30 AM	East Sidney Feeder 4	Complete	Blink Coun
	Pioneer	2-Nov-2006 3:00:22 AM	2-Nov-2006 3:12:09 AM	East Casstown Feeder 4	Complete	Blink Coun
	jhickman	2-Nov-2006 3:00:21 AM	2-Nov-2006 3:24:27 AM	McCarytvilleFd3Blinks	Complete	Blink Coun
	jhickman	2-Nov-2006 3:00:21 AM	2-Nov-2006 3:19:38 AM	McCarytvilleFd2Blinks	Complete	Blink Coun
	jhickman	2-Nov-2006 3:00:20 AM	2-Nov-2006 3:22:33 AM	EagleFdr3Blinks	Complete	Blink Coun
	jhickman	2-Nov-2006 3:00:19 AM	2-Nov-2006 3:21:42 AM	EagleFdr2Blinks	Complete	Blink Coun
	jhickman	2-Nov-2006 3:00:19 AM	2-Nov-2006 3:12:44 AM	EagleFdr4Blinks	Complete	Blink Coun
	jhickman	2-Nov-2006 3:00:18 AM	2-Nov-2006 3:14:40 AM	East Sidney Frd3 Blinks	Complete	Blink Coun
	jhickman	2-Nov-2006 3:00:18 AM	2-Nov-2006 3:05:04 AM	McCarytvilleFd1Blinks	Complete	Blink Coun
	jhickman	2-Nov-2006 3:00:17 AM	2-Nov-2006 3:09:18 AM	HaltermanFdr3Blinks	Complete	Blink Coun
	jhickman	2-Nov-2006 2:30:12 AM	2-Nov-2006 2:37:00 AM	East Sidney Fdr 2 Blinks	Complete	Blink Coun
	jhickman	2-Nov-2006 2:30:12 AM	2-Nov-2006 2:39:37 AM	HaltermanFdr2Blinks	Complete	🛛 Blink Coun 🗸
	<					>
1	Show only F	Events beginning with:				
	OK	Refresh C	ancel Job 📗 Delete Job			Cancel










Outage# 4182 Daterme On: 11020206 0455 MM Connectivity Type: OH Number Out 1 Daterme On: 11020206 062 28 MM Account# 20703 Stabis: Restored Cause: ACCOUNTS; OTHER 4200900 0 Type: B Stabis: Restored Vinder Out 11020206 062 28 MM Account# 4200900 Type: Meter Equipment NUCHOR OR OUY Transforme#; 31105321 0 Connectivity: Oge Or Out Outage: Transforme#; 31105321 0 Phase: B Outage: Transforme#; 31105321 0 Connectivity: Actual Ntr Out Weather: 0 0 Phase: B Outage: Temperature: 0 Dispatch Comments: Cerew Info Crew Info Crew Outage: Time Or Site: User:
Number Out 1 Date/Time Ont 11022006 © 05 29 A/M Account #: 2027/33 Status: Restored Cause: Account #: 2020/33 4208980 Phase: B Section Name: 0 Transformer #: 01050512 Phase: Sub C dl: Fdr C dl: Pro DW: Actual Nor Out Wesher: - Phase: Sub C dl: Fdr C dl: Pro DW: B 20 3 VSA-5203 Dispatch Comments: Correctivity: Wesher: Wesher: - - Dispatch Comments: Core // Outage: Time 0n5 Site: User: - Dispatch Comments: Crew: Outage: Time 0n5 Site: User:
Shuk: estored ACCHOR RO, OTHER Meter # 4200000 Type: Meter # Equipment Equipment 0105321 Phase: B OB2-75-011 OB OB 0105321 ConnectMy Tan: OB OB OB OB Phase: Sub.Cd: Fdr.Cd: Pro.Dec Detent Cd: OB Phase: Sub.Cd: Fdr.Cd: Pro.Dec Temperture: Major Storm: OB Image: Sub.Cd: Fdr.Cd: Pro.Dec Fdr.Cd: Temperture: OB Image: Sub.Cd: Fdr.Cd: Secton Narry URD OCRC Crew Info Time On-Site: User. Image: Sub.Sc: Secton DARY URD CRC Crew Info Time On-Site: User. Image: Secton DARY URD CRC Secton DARY URD Crew Image: Time On-Site: User. Image: Image: Image: Image: Image: Image: Image: Image: Image: Image: Image: Image: Image: Image:
Weier Comments Equipment ANCHOR OR GUY Tarscination 0 02x75-011 0 <
Phase: B Uccation: U22/75:011 ConnectMy Phase: Sub Cd: Phase: Sub Cd: Phase: Sub Cd:
Localon: 092-75-011 ConnectMy Phase: Sub Cd: Fdr Cd: Pro Dv:: B 20 3 VGA-5203 CeteVinte CeteVin
ConnectMdy Actual Nbr Out Phase: Sub Cd: Phase: Sub Cd: Phase: Sub Cd: Propriation: Temperature: Windy: Major Storm: Dispatch Comments: User: Crew Info Crew: Outage: Time Off-Site: User: Crew: Outage: Time Off-Site: User: Crew: Outage: Time Off-Site: User: Crew: Outage: Time Off-Site: User: Crew: Outage: Time Off-Site: User: Crew: Outage: Time Off-Site: User: Crew: Outage: Time Off-Site: User: Crew: Outage: Time Off-Site: User: Crew: Outage: Time Off-Site: User: Crew: Outage: Time Off-Site: User: Time Off-Site: Outage:
Phase Sub Cd: Fdr Cd: Pro Dve: B 20 3 VSA-5203 Dispatch Comments Crew Info Dispatch Comments: CRC User: Crew Info Crew Outage: Time On-Site: Time Off-Site: BAD SECONDARY URD CRC Image: Image: Image:
B 20 3 VBA-5203 Set Device Windy: Dispatch Comments Crew Info Crew Outage: Time Assigned: Time On-Site: Time Off-Site: User: BAD SECONDARY URD CRC Crew. Outage: Time Assigned: Time On-Site: Time Off-Site: User: BAD SECONDARY URD CRC Crew. Outage: Time Assigned: Time Off-Site: User: BAD SECONDARY URD CRC Crew. Outage: Time Assigned: Time Off-Site: User: BAD SECONDARY URD CRC Crew. Outage: Time Assigned: Time Off-Site: User: BAD SECONDARY URD CRC Crew. Outage: Time Assigned: Time Off-Site: User: BAD SECONDARY URD CRC Crew. Outage: Time Assigned: Time Off-Site: User:
Dispatch Comments Crew Info Time: Comments: User: Crew Outage: Time Off-Site: User: BAD SECONDARY URD CRC EAdd The Delete
Dispatch Comments Time: Comments: CRC BAD SECONDARY URD CRC Add Delete Crew Info Crew Info Crew Coutage: Time Assigned: Time On-Site: User: Crew Info Crew Coutage: Time Assigned: Time On-Site: User: Crew Info Crew
Dispatch Comments Time: Comments: CRC BAD SECONDARY URD CRC Add Delete Crew Info Crew Info Crew Coutage: Time Assigned: Time On-Site: User: Crew Info Crew Coutage: Time Assigned: Time On-Site: User: Crew Info Crew
Time: Comments: User: BAD SECONDARY URD CRC BAD SECONDARY URD CRC Image: Time Assigned: Time Ort-Site: Time Ort-Site: Time Ort-Site: User: Image: Time Assigned: Image: Time Assigned: Time Ort-Site: User: Image: Time Assigned: Image: Time Assigned: Time Ort-Site: Image: Time Assigned: Image: Time Assigned: Image: Time Assigned: Time Ort-Site: Image: Time Assigned: Image: Time Assigned: Image: Time Assigned: Image: Time Ort-Site: Image: Time Assigned: Image: Time Ort-Site: Image: Time Assigned: Image: Time Assigned: Image: Time Assigned: Image: Time Assigned: Image: Time Assigned: Image: Time Assigned: Image: Time Assigned: Time Assigned: Image: Time Assigned: Image: Time Assigned: Time Assigned: Time Assigned: Time Assigned: Image: Time Assigned: Image: Time Assigned: Time A
BAD SECONDARY URD CRC
Add Toelete
Image: Save Close
The Contract Device Direct Contract Direct Dire
 * First Name: Last Name: Time Called: User: Line Sect. Phs: Trf: Meter: Service Map Lo Comments: Comments: Columbus JACKSON 4:59:09 AM 11/2/2006 CRC 2049 B B11053621 46208990 092-75-011 SAME ACCT HAS NO POWER TO LIGHT IN GARAGE, HEAT OTHER AL
T Phone Calls
🔁 0 🔿 Medical Alert
H 1 O All Consumers
💦 0 🔿 Call Back




>





Another Partial Power Outage





Select Outage Event



User	▼ Started	Completed	Outage Event Name	Status	Detection 🔼
jhickman	1-Nov-2006 10:30:13 AM		Route 66 FDR2 Blinks	Running	Blink Coun
jhickman	1-Nov-2006 10:30:12 AM		HaltermanFdr2Blinks	Running	Blink Coun
jhickman	1-Nov-2006 10:30:11 AM	1-Nov-2006 10:36:45 AM	EastCassF2Blinks	Complete	Blink Coun
jhickman	1-Nov-2006 10:30:11 AM	1-Nov-2006 10:36:54 AM	East Sidney Fdr 2 Blinks	Complete	Blink Coun
NISC	1-Nov-2006 10:18:52 AM	1-Nov-2006 10:19:10 AM	OD_OA-ping	Complete	Ping
NISC	1-Nov-2006 10:18:49 AM	1-Nov-2006 10:19:04 AM	OD_OA-ping	Complete	Ping
NISC	1-Nov-2006 10:16:43 AM	1-Nov-2006 10:17:07 AM	OD_OA-ping	Complete	Ping
NISC	1-Nov-2006 10:16:43 AM	1-Nov-2006 10:17:01 AM	OD_OA-ping	Complete	Ping
jhickman	1-Nov-2006 10:00:15 AM	1-Nov-2006 10:10:34 AM	Route 66 FDR1 Blinks	Complete	Blink Coun
Pioneer	1-Nov-2006 10:00:15 AM	1-Nov-2006 10:06:23 AM	East Sidney Fdr 1Blinks	Complete	Blink Coun
jhickman	1-Nov-2006 10:00:14 AM	1-Nov-2006 10:15:48 AM	Halterman Fdr 1 Blinks	Complete	Blink Coun
jhickman	1-Nov-2006 10:00:13 AM	1-Nov-2006 10:07:14 AM	ECassFdr1Per	Complete	Blink Coun
NISC	1-Nov-2006 8:52:16 AM	1-Nov-2006 8:59:01 AM	OD_OA-ping	Complete	Ping
Pioneer	1-Nov-2006 3:30:22 AM	1-Nov-2006 3:34:26 AM	East Sidney Feeder 4	Complete	Blink Coun
Pioneer	1-Nov-2006 3:00:23 AM	1-Nov-2006 3:12:36 AM	East Casstown Feeder 4	Complete	Blink Coun 🗸
<		ш			>
Show only I	Events beginning with:				
ОК	Refresh	Cancel Job Delete Job		[Cancel
				·	





>

Job Status: Time Job Started: Time Job Finished: Outage Display Blink Display Voltage Display Hierarchy List	1-No 1-No () () () F	plete v-2006 10 v-2006 10 Current Sta Previous S Driginal St	l:19:10 Al atus Status	- Refres	to Refresh	econds nutes		sh Now cel Job
EAGLE (32)	BUS	Feeder FDR2 FDR2 FDR2	Phase A A	 Status Online Online Online	Meter Numb 45754407 45754409 45754412	er Custome 190001 190102 190202	er Acct.	Premises 081-79-00 082-50-00 082-50-00

<







(: 1657188.525273 Y: 786360.954946

Display 4.32 Miles



Cost Savings on the Outage Management Side

- Crew call out after hours \$350 per occurrence
- After an outage has been restored all meters are immediately checked – crew does not have to return to the area later
- With AMR integration the scope of the outage is more quickly determined



In Summary

- During early stages of development only some of the data fields are being sent across by MultiSpeak
- Business processes need to become more real time in the utility
- Databases need to compare occasionally to make sure that they are synchronized
- Utilities must play an active role as venders do their development work

Contact Information

Pioneer Electric Cooperative Tom Musick Director of Operations P.O. Box 604 Piqua, OH 45326 Office 937-773-2523 tmusick@pioneerec.com

Fairview Consulting, LLC John Hickman President/CEO 7622 Fairview Rd. Piqua, OH 45356 Cell 937-214-2643 jhickman@fairviewconsultingllc.com National Information Solutions Cooperative Randy Schroder Utility E-Solutions Manager One Innovation Circle Lake St. Louis, MO 63367 Office 866-999-6472 randy.schroder@nisc.cc

Distribution Control Systems, Inc. Bob Richardson Senior Vice President of New Business Development 945 Hornet Drive Hazelwood, MO 63042 Office 314-895-6400 brich@twacs.com